

LCCR**Lead Service Line Inventory****(LSLI)**

PWS Name:

PWS ID:

NE31-

Operators signature:

Date:

#	Location identifier / Address	System-Owned Classification	Method of Determination	Customer-Owned Classification	Method of Determination	Lead Present
1	1830 Co Rd A			Customer selfidentified copper	visual	
2	101 Main #2			Customer self identified copper	visual	
3	101 Main #1			Customer se lidentified copper	visual	
4	812 Spruce	PVC/Copper	built after 1988			
5	420 Beech			customer self identified galvanized steel	visual	
6	129 5th Ave			customer self identified copper	scratch	
7	125 5th Ave			customer self identified plastic	visual	
8	121 5th Ave			customer self identified copper	visual	
9	117 5th Ave			customer self identified copper	visual	
10	113 5th Ave			customer self identified lead	scratch test	x
11	109 5th Ave			customer self idntidentified plastic	visual	
12	105 5th Ave			customer self identified copper	visual	
13	104 5th Ave			customer self identified copper	visual	
14	108 5th Ave			customer self identified copper	scratch	
15	112 5th Ave			customer self identified copper	visual	
16	120 S 5th			customer self identified copper	visual	
17	124 5th ave			customer self identified copper	visual	
18	126 5th Ave			CUSTOMER SELF IDENTIFIED COPPER	VISUAL	
19	504 Beech			customer self identified copper	scratch	
20	508 W Beech			customer self identified copper	visual	
21	209 Laura Lane			customer self identified copper	visual	
22	205 Laura Lane					
23	121 Laura Lane					
24	117 Laura Lane			customer self identified copper	visual	
25	113 Laura Lane			customer self identified copper	visual	
26	109 Laura Lane					

#	Location identifier / Address	System-Owned Classification	Method of Determination	Customer-Owned Classification	Method of Determination	Lead Present
27	105 Laura Lane			customer self identified copper	visual	
28	104 Laura Lane			customer self identified copper/plastic	visual	
29	108 Laura Lane			customer self identified copper/plastic	visual	
30	112 Laura Lane			customer self identified copper	visual	
31	116 Laura Lane			customer self identified copper	visual	
32	120 Laura Lane			customer self identified copper	visual	
33	204 Laura Lane			customer self identified copper/plastic	visual	
34	208 Laura Lane					
35	212 Laura Lane					
36	304 Laura Lane			Customer self identified copper	visual	
37	308 Laura Lane			customer self identified copper	visual	
38	504 Elm			customer self identified copper	visual	
39	508 W Elm			customer self identified copper	visual	
40	512 W Elm			customer self identified copper	visual	
41	516 Elm			Customer self identified copper	visual	
42	520 Elm			customer self identified copper/plastic	visual	
43	316 7th			customer self identified copper	visual	
44	312 7th			customer self identified copper	visual	
45	308 7th					
46	304 7th			customer self identified plastic	visual	
47	212 7th					
48	208 7th			customer self identified copper	visual	
49	204 7th			customer self identified copper	scratch	
50	517 Beech			customer self identified copper	visual	
51	700 Beech					
52	704 Beech			customer self identified copper	scratch	
53	708 Beech			customer self identified copper	visual	
54	712 Beech			customer self identified copper	visual	
55	713 Spruce			customer self identified copper	visual	
56	709 Spruce			customer self identified copper	visual	

#	Location identifier / Address	System-Owned Classification	Method of Determination	Customer-Owned Classification	Method of Determination	Lead Present
57	705 Spruce			Customer self identified copper	visual	
58	701 Spruces Circle			customer self identified copper	visual	
59	700 Spruce			customer self identified copper	visual	
60	704 Spruce			customer self identified copper	Visual	
61	708 Spruce circle			customer self identified copper	scratch	
62	105 Precinct			customer self identified copper	visual	
63	311 Precinct	PVC/Copper	built after 1988	customer self identified copper	visual	
64	308 8th	PVC/Copper	built after 1988	customer self identified copper	visual	
65	711 Beech			customer self identified copper	visual	
66	209 8th			customer self identified copper	visual	
67	213 8th			customer self identified copper	visual	
68	305 8th			customer self identified copper	visial	
69	309 8th			customer self identified copper	visual	
70	313 8th			customer self identified copper	visual	
71	317 8th			customer self identified copper	visual	
72	721 Elm			customer self identified copper	visual	
73	717 Elm					
74	713 Elm					
75	709 Elm			customer self identified copper	visual	
76	705 Elm			customer self identified copper	visual	
77	525 Elm			Customer self identified copper	visual	
78	709 Elm			customer self identified copper	visual	
79	515 Elm			Customer self identified lead	scratch test	x
80	513 Elm			customer self identified copper	visual	
81	509 Elm			Customer self identified copper	visual	
82	505 Elm			customer self identified copper	visual	
83	408 Laura Lane			Customer self identified copper	visual	
84	508 Pine					
85	512 Pine			Customer Self identified galvanized steel	visual	
86	516 Pine			Customer self identified galvanized steel	visual	
87	520 Pine			Customer Self Identified copper	visual	

#	Location identifier / Address	System-Owned Classification	Method of Determination	Customer-Owned Classification	Method of Determination	Lead Present
88	524 Pine			Customer Self Identified copper	visual	
89	528 Pine			Customer Self Identified coppeer	visual	
90	604 Pine			customer self identified	visual	
91	608 Pine			Customer Self identified copper	visual	
92	612 Pine			Customer Self identified copper	scratch	
93	616 Pine			customer self identified copper	visual	
94	620 Pine					
95	704 Pine			Customer Self Identified copper	visual	
96	720 Pine			Customer Self Identified plastic	visual	
97	413 Laura Lane					
98	409 Laura Lane			Customer Self Identified copper	visual	
99	#6 Elm Place			Customer Self Identified copper	visual	
100	#5 Elm Place			Customer Self Idnetified copper	visual	
101	#4 Elm Place					
102	#3 Elm Place					
103	#2 Elm Place					
104	309 Laura Lane			Customer Self Identified copper	visual	
105	305 Laura Lane			customer self identified copper	visual	
106	425 Beech			Customer Self Identified copper	scratcg	
107	421 Beech			Customer Self Identified copper	visual	
108	417 Beech			Customer Self Identified copper	plumbing records	
109	305 7th	PVC/Copper	built after 1988	Customer Self identified copper	visual	
110	712 W Spruce	PVC/Copper	built after 1988	Customer Self Identified plastic	visual	
111	816 W Spruce	PVC/Copper	built after 1988			
112	315 Precinct	PVC/Copper	built after 1988	customer self identified plastic	visual	
113	527 Pine	PVC/Copper	built after 1988	Customer Self Identified copper	visual	
114	805 Spruce	PVC/Copper	built after 1988	Customer Self Identified copper	visual	
115	204 8th street	PVC/Copper	built after 1988	Customer Self Identified copper	visual	
116	319 Precinct	PVC/Copper	built after 1988	Customer Self Identified copper	visual	
117	201 Precinct	PVC/Copper	built after 1988	Customer Self Identified copper	visual	

#	Location identifier / Address	System-Owned Classification	Method of Determination	Customer-Owned Classification	Method of Determination	Lead Present
119	113 Precinct	PVC/Copper	built after 1988	Customer Self Identified copper	visual	
120	304 8th	PVC/Copper	built after 1988	Customer Self Identified copper	visual	
121	210 8th street	PVC/Copper	built after 1988	Customer Self Identified copper	visual	
122	112 8th	PVC/Copper	built after 1988	Customer self identified copper	visual	
123	808 W Spruce	PVC/Copper	built after 1988			
124	312 8th	PVC/Copper	built after 1988	Customer self identified copper	visual	
125	316 8th	PVC/Copper	built after 1988	Customer Self identified copper	visual	
126	804 Spruce	PVC/Copper	built after 1988	Customer self identified copper	visual	
127	216 8th	PVC/Copper	built after 1988			
128	208 W Beech			Customer self identified copper	plumbing records	
129	212 Beech			Customer self identified copper	visual	
130	216 W Beech			customer self identified copper/plastic	visual	
131	220 Beech			Customer self identified copper	visual	
132	224 W Beech					
133	300 W Beech					
134	404 Beech	PVC/Copper	built after 1988	Customer self identified copper	visual	
135	408 W Beech			Customer self identified galvanized steel	visual	
136	416 Beech			Customer self identified copper	visual	
137	413 Beech			Customer self identified copper	plumbing records	
138	409 Beech			customer self identified copper/plastic	visual	
139	304 4th	PVC/Copper	84 improve	customer self identified plastic	visual	
140	305 4th	PVC/Copper	84 improve	lead	visual	x
141	309 S 4th	PVC/Copper	84 improve		visual	
142	313 4th	PVC/Copper	84 improve	customer self identified copper	visual	
143	304 3rd			Customer self identified copper	visual	
144	312 S 3rd			Customer selfidentified copper		
145	225 Beech			Customer self identified copper	visual	
146	413 S 2nd			customer self identified copper	visual	
147	Ernies			customer self identified galvanized steel	visual	
148	304 S 2nd			customer self identified galvanized steel	visual	

#	Location identifier / Address	System-Owned Classification	Method of Determination	Customer-Owned Classification	Method of Determination	Lead Present
149	Erries			customer self identified galvanized steel	visual	
150	Erries			customer self identified galvanized steel	visual	
151	Erries			customer self identified galvanized steel	visual	
152	Erries			customer self identified galvanized steel	visual	
153	224 Elm			customer self identified galvanized steel	visual	
154	232 Elm			customer self identified all	visual	
155	322 S 3rd					
156	405 S 3rd			customer self identified copper	visual	
157	217 W Elm			customer self identified copper		
158	SweetPea 208 Pine					
159	Covenant Church			Customer self identified copper	visual	
160	220 Pine			Customer self identified copper	Scratch test	
161	228 Pine			customer self identified plastic		
162	312 Pine			lead	visual	x
163	324 Pine	PVC/Copper	84 improve			
164	405 s 4th	PVC/Copper	84 improve	customer self identified copper/plastic	visual	
165	316 Elm	PVC/Copper	84 improve	Customer self identified copper	visual	
166	316 S 4th	PVC/Copper	84 improve	customer self identified copper	scratch	
167	404 S 4th	PVC/Copper	84 improve	customer self identified plastic	visual	
168	420 4th	PVC/Copper	84 improve	customer self identified copper	scratch	
169	412 Pine			customer self identifeid copper	scratch	
170	420 Pine					
171	413 Pine			customer self identified galvanized steel	visual	
172	504 s 4TH			customer self identified COPPER	VISUAL	
173	512 S 4th			customer self identified copper/plastic	visual	
174	516 S 4th			customer self identified galvanized steel	plumbing records	
175	520 S 4th			customer self identified copper	visual	
176	604 S 4th			customer self identified copper	visual	
177	608 S 4th			customer self idnetified plastic	visual	
178	624 S 4th					

#	Location identifier / Address	System-Owned Classification	Method of Determination	Customer-Owned Classification	Method of Determination	Lead Present
179	613 S 4th	PVC/Copper	built after 1988	customer self identified copper	visual	
180	605 4th			customer self identified galvanized	steel	
181	525 s 4th			customer self identified copper	visual	
182	515 4th			customer self identified copper	scratch	
183	321 Pine			customer self identified copper	visual	
184	313 Pine					
185	305 Pine			customer self identified copper	scratch	
186	229 W Pine			Customer self identified copper	visual	
187	221 Pine			lead	scratch test	x
188	217 Pine			Customer Self identified copper	visual	
189	213 W Pine			Customer self identified copper	scratch test	
190	209 Pine	PVC/Copper	built after 1988	customer self identified copper	visual	
191	520 S 2nd			customer self identified copper	scratch test	
192	212 Ash			Customer self identified copper	plumbing records	
193	220 Oak			Customer self identified copper	scratch test	
194	217 Oak			customer self identified copper	visual	
195	604 S 2nd			Customer self identified copper	visual	
196	612 s 2nd			customer self identified copper	visual	
197	204 Ash					
198	704 S 2nd			customer self identified copper	visual	
199	712 S 2nd			customer self identified copper	visual	
200	720 S 2nd			customer self identified copper	visual	
201	804 s 2nd			customer self identified galvanized steel	visual	
202	707 S 2nd			customer self identified copper	visual	
203	705 S 2nd					
204	621 S 2nd			customer self identified copper	visual	
205	617 S 2nd			customer self identified galvanized Steel	visual	
206	605 S 2nd			customer self identified copper	visual	
207	104 Oak			customer self identified copper	scratch	
208	108 Oak			customer self identified copper	visual	
209	517 S 2nd					

#	Location identifier / Address	System-Owned Classification	Method of Determination	Customer-Owned Classification	Method of Determination	Lead Present
211	501 S 2nd	PVC/Copper	84 improve			
212	117 Pine	PVC/Copper	84 improve	customer self identified copper	visual	
213	113 W Pine	PVC/Copper	84 improve	customer self identified copper	visual	
214	105 W Pine	PVC/Copper	84 improve	Customer self identified copper	visual	
215	321 S 1st			customer self identified copper	scratch test	
217	104 Pine	PVC/Copper	84 improve	customer self identified copper	visual	
218	108 Pine	PVC/Copper	84 improve	customer self identified copper	visual	
219	112 Pine	PVC/Copper	84 improve	customer self identified Gs/Copper	visual	
220	116 W Pine	PVC/Copper	84 improve	customer self identified plastic	visual	
221	124 Pine	PVC/Copper	84 improve	customer self identified copper	visual	
223	421 S 2nd					
224	413 S 2nd #2			customer self identified copper	visual	
225	401 S 2nd			customer self identified copper	visual	
226	119 W Elm					
329	208 Edwin			Customer self identified GS/copper	visual	
230	116 Elm			customer self identified plastic	visual	
232	130 Elm	PVC/Copper	built after 1988	customer self identified copper	visual	
233	313 S 2nd			customer self identified copper	scratch	
234	305 S 2nd			customer self identified galvanized steel		
236	113 Beech			customer self identified plastic	visual	
237	108 Beech			Customer self identified copper	visual	
238	304 S 1st	PVC/Copper	84 improve			
239	321 S 1st office			customer self identified copper	scratch	
241	104 W Beech	PVC/Copper	84 improve	customer self identified copper	plumbing records	
242	108 W Beech			customer self identified copper	visual	
243	112 W Beech			customer self identified plastic	plumbing records	
244	116 & 118 W Beech	PVC/Copper	built after 1988			
245	120 Beech			customer self identified copper	visual	
246	355 Co Rd 18			customer self identified copper	visual	
250	370 Co Rd 18	PVC/Copper	built after 1988			

#	Location identifier / Address	System-Owned Classification	Method of Determination	Customer-Owned Classification	Method of Determination	Lead Present
252	1789 Co Rd A					
253	1779 Co Rd A			customer self identified copper/plastic	plumbing records	
254	104 N hwy 77			customer self identified copper	visual	
255	216 E Elm					
257	321 S 1st shop			customer self identified plastic	scratch	
258	317 S Hwy 77	PVC/Copper	built after 1988			
259	216 S 1st			customer self identified plastic	visual	
260	413 S 2nd #3			customer self identified copper	visual	
261	717 S 2nd					
262	721 S 2nd			customer self identified copper	visual	
263	725 S 2nd	PVC/Copper	built after 1988			
264	216 S 2nd	PVC/Copper	built after 1988	customer self identified copper	Visual	
265	416 S 2nd	PVC/Copper	built after 1988	customer self identified copper	plumbing records	
266	625 S 4th	PVC/Copper	built after 1988	customer self identified copper	visual	
267	621 S 4th	PVC/Copper	built after 1988			
268	512 S 2nd	PVC/Copper	built after 1988	customer self identified copper	visual	
274	101 Main #4			customer self identified copper	visual	
206	605 S 2nd			customer self identified copper	visual	
275	205 S 2nd			customer self identified copper	visual	
276	201 S 2nd			customer self identified copper	visual	
277	121 Spruce					
278	117 W Spruce			customer self identified copper	scratch	
279	113 Spruce			lead		X
280	117 S 2nd			customer self identified galvanizes steel	scratch	
281	120 Spruce					
282	116 Spruce					
283	112 Spruce					
284	108 Spruce			customer self identified copper	visual	
285	104 W Spruce			customer self identified copper	visual	
286	105 E Main					
287	101 Main # 3			customer self identified copper	visual	

#	Location identifier / Address	System-Owned Classification	Method of Determination	Customer-Owned Classification	Method of Determination	Lead Present
288	117 W Main	?		customer self identified copper	visual	
289	121 W Main			customer self identified copper		
290	125 W Main			customer self identified	scratch	
291	105 S 2nd			customer self identified copper	visual	
292	120 W main					
293	116 W Main			customer self identified copper	scratch	
294	112 W Main					
295	108 W Main			customer self identified copper	visual	
296	104 W Main	?		customer self identified copper	visual	
297	100 Main					
299	117 N Archie	PVC/Copper	84 improve			
300	County Shed			customer self identified copper	visual/scratch	
301	116 Edwin			Customer self identified galvanized steel	visual	
302	201 N Archie			customer self identified copper	visual	
303	216 Archie	PVC/Copper	84 improve	customer self identified copper	visual	
304	120 Cameron	PVC/Copper	built after 1988			
305	350 Archie	PVC/Copper	84 improve	customer self identified plastic	visual	
306	104 W Purdum	PVC/Copper	84 improve	customer self identified galvanized steel	visual	
307	105 Park	PVC/Copper	84 improve	customer self identified plastic	visual	
308	505 Archie	PVC/Copper	84 improve	customer self identified plastic		
309	500 Archie	PVC/Copper	84 improve			
310	108 W Park	PVC/Copper	84 improve	customer self identified copper	visual	
311	112 Prudum			customer self identified copper	visual	
312	116 Park			customer self identified copper	visual	
313	120 Park			customer self identified copper	visual	
314	421 S 2nd Methodist Church					
315	124 Cameron			customer self identified copper	visual	
316	204 Cameron			customer self identified copper	visual	
317	208 W Cameron					
318	216 N 2nd			customer self identified copper		

#	Location identifier / Address	System-Owned Classification	Method of Determination	Customer-Owned Classification	Method of Determination	Lead Present
319	216 N 2nd			customer self identified copper	visual	
320	217 Cameron			customer self identified copper	visual	
321	216 Cameron			customer identified copper/plastic		
322	228 Cameron			customer self identified copper	visual	
323	225 W Cameron					
324	224 Edwin					
325	229 W Edwin					
326	221 W Edwin			customer self identified copper	scratch test	
327	217 Edwin			customer self identified copper	scratch test	
328	212 Edwin			customer self identified copper	visual	
329	208 Edwin			customer self identified copper/GS		
330	204 Edwin					
331	217 N 2nd			customer self identified copper/plastic		
332	128 W Edwin			customer self identified plastic	visual	
333	125 Cameron			customer self identified plastic	visual	
334	121 Cameron			customer self identified copper	visual	
335	120 Edwin			customer self identified copper	visual	
336	117 Cameron			customer self identified copper	visual	
338	108 Edwin			customer self identified copper	visual	
339	104 Edwin			customer self identified galvanized steel	visual	
340	116 Archie	PVC/Copper	84 improve	customer self identified copper	visual	
341	109 Ewdin			customer self identified copper	visual	
342	113 W Edwin					
343	117 W Edwin	PVC/Copper	built after 1988			
344	121 Edwin			customer self identified copper	visual	
345	125 W Edwin			customer self identified copper	visual	
346	117 n 2nd	PVC/Copper	built after 1988	customer self identified plastic	visual	
347	109 N 2nd			customer self identified copper	visual	
348	116 N 2nd			customer self identified plastic	visual	
349	112 N 2nd			customer self identified copper	visual	
350	204 W Main					

#	Location identifier / Address	System-Owned Classification	Method of Determination	Customer-Owned Classification	Method of Determination	Led Present
351	212 Main			customer self identified copper	visual	
352	216 W Main Lutheran Church			customer self identified copper	visual	
355	112 N 3rd			customer self identified galvanized steel	visual	
354	116 N 3rd			customer self identified copper	visual	
356	104 N 3rd			customer self identified copper	visual	
357	417 Main			customer self identified copper	visual	
358	409 W Main	PVC/Copper	built after 1988			
359	301 W Main					
360	114 S 3rd School					
361	213 Main	PVC/Copper	built after 1988	customer self identified copper	visual	
362	205 Main					
363	112 S 2nd			customer self identified copper	visual	
364	116 S 2nd			customer self identified plastic	visual	
365	208 Spruce					
366	225 Spruce			customer self identified copper	visual	
367	221 Spruce			customer self identified copper	visual	
368	217 Spruce					
369	209 Spruce			customer self identified copper	visual	
370	204 S 2nd					
371	208 S 2nd			Galvanized Steel	visual	
350	204 Main					
372	216 S 2nd			customer self identified copper	visual	
373	220 S 2nd			customer self identified copper	visual	
374						
375	420 Co Rd 18					
377	112 Park	PVC/Copper	built after 1988	customer self identified copper	plumbing records	
378	111 Purdum	PVC/Copper	built after 1988			
381	317 Main	PVC/Copper	built after 1988	Galvanized Steel	visual	
384	325 W Main	PVC/Copper	built after 1988			
387	740 S 3rd	PVC/Copper	built after 1988	customer self identified plastic	visual	

#	Location identifier / Address	System-Owned Classification	Method of Determination	Customer-Owned Classification	Method of Determination	Lead Present
388	713 S 3rd	PVC/Copper	built after 1988			
389	712 S 3rd	PVC/Copper	built after 1988	customer self identified copper	visual	
390	208 Ash	PVC/Copper	built after 1988	customer self identified plastic	visual	
393	316 W Beech	PVC/Copper	built after 1988			
394	757 S 3rd	PVC/Copper	built after 1988	customer self identified copper	visual	
395	440 E Elm	PVC/Copper	built after 1988			
396	753 S 2nd	PVC/Copper	built after 1988	customer self identified plastic	visual	
397	720 S 3rd	PVC/Copper	built after 1988	Customer self identified galvanized steel	visual	
398	741 S 3rd	PVC/Copper	built after 1988	customer self identified copper	visual	
401	705 S 3rd	PVC/Copper	built after 1988	customer self identified plastic	visual	
402	721 S 3rd	PVC/Copper	built after 1988	customer self identified copper/plastic	visual	
403	219 Oak	PVC/Copper	built after 1988	customer self identified plastic	visual	
405	405 Archie	PVC/Copper	84 improve			
406	355 Archie	PVC/Copper	built after 1988			
407	444 W Pine	PVC/Copper	built after 1988	customer self identified plastic	visual	
408	228 Ash	PVC/Copper	built after 1988	customer self idecopper	scratch	
409	704 S 3rd	PVC/Copper	built after 1988	customer self identified plastic	visual	
410	113 N 3rd	PVC/Copper	built after 1988	customer self identified plastic	visual	
411	620 S 4th	PVC/Copper	built after 1988	customer self identified plastic	visual	
412	206 Ash	PVC/Copper	built after 1988	customer self identified plastic	plumbing records	
413	430 Co Rd 18	PVC/copper	tapped 2017			
450	120 N 3rd	PVC/Copper	built after 1988	customer self identified copper	visual	
451	124 N 3rd	PVC/Copper	built after 1988			
452	108 Hunter	PVC/Copper	built after 1988			
453	112 Hunter	PVC/Copper	built after 1988	customer self identified plastic	visual	
454	116 Hunter	PVC/Copper	built after 1988	Galvanized Steel	visual	
455	115 Hunter	PVC/Copper	built after 1988	customer self identified plastic	visual	
456	119 Hunter	PVC/Copper	built after 1988	customer self identified plastic	visual	
457	120 Hunter	PVC/Copper	built after 1988			
458	124 Hunter	PVC/Copper	built after 1988			
459	123 Hunter	PVC/Copper	built after 1988			

#	Location identifier / Address	System-Owned Classification	Method of Determination	Customer-Owned Classification	Method of Determination	Lead Present
460	127 Hunter	PVC/Copper	built after 1988	customer self identified plastic	visual	
461	128 Hunter	PVC/Copper	built after 1988			
462	132 Hunter	PVC/Copper	built after 1988	customer self identified copper	visual	
465	136 Hunter	PVC/Copper	built after 1988	customer self identified copper	visual	
466	140 Hunter	PVC/Copper	built after 1988	customer self identified plastic	visual	
467	301 Park	PVC/Copper	built after 1988	customer self identified plastic	visual	
468	304 Park	PVC/Copper	built after 1988	customer self identified plastic	visual	
469	308 Park	PVC/Copper	built after 1988			
470	312 Park	PVC/Copper	built after 1988	customer self identified copper	visual	
471	316 Park	PVC/Copper	built after 1988	customer self identified plastic	visual	